




RAMayes

Tri-Fold Method for Foil Shielding



Notes:

1. Adhere RF Foil Shielding to Substrate Fully, using Adhesive or PSA.
2. If Tri-Fold Method is Not Feasible, we Recommend Overlapping Foil and Seam Tape with Electrically Conductive PSA (ECPSA) Foil Tape.
3. Tri-Fold Method Can be used on All Al, Cu & Stainless-Steel Foil, 5 mil Thick or Less.